

Maintenance Guide

Omnisports Vinyl

24 10 2012



NOTA BENE

The Omnisports products are factory treated with the innovative Topclean X-trem performance (XP™). Topclean XP™ is a UV-reticulated polyurethane treatment, reinforced with micro-alumina particles which offer an excellent resistance to wear and tear.

Please note that to provide the end-customer with the best use of the flooring, the maintenance procedure must carefully be followed.

If not, Tarkett Sports will decline all potential damages following a non appropriate maintenance procedure.

General advices

The players must wear appropriate shoes with white soles dedicated to Indoor Sports practise.

It is strongly recommended to install a doormats at the entrance of the gymnasium.

Tarkett recommends Emco mats.

These mats can be built up with different materials, that help to catch humidity, dirt, dust....:

A griddy part, that allows to remove gravels, ground particles...,

A synthetic part to catch dust under soles,

A textile part dedicated to absorption of humidity.

Emco France SAS - 8 rue des perrières Z.I.- 39700 Dampierre

Tel : +333 84 80 16 20/Fax :+333 84 80 16 21/E-mail: info@emco.fr

Daily manual cleaning

Consists in removing dust and gravels by sweeping or vacuum cleaning.

Periodical care

Machine cleaning: use an automatic scrubber machine fitted out with white soft brushes or white pads.

Recommend autoscrubber: Rotowash B60 manufactured by Rotowash Company.

A floor-cleaner(pH7 to 9) is convenient (dilution 1%), our advice:

Dynatech Trophy – Tana Professional : 3 Avenue du Canada - 91940 Les Ulis

Tél : +331 69 18 95 30 / Fax : +331 69 28 23 54 / Email : professionalfrance@werner-mertz.com

Jontec Asset – Johnson Diversey - johnsondiversey.com

Rotowash France : 41 rue du Mûrier - Equatop - 37540 St Cyr sur Loire

Tél : 02 47 41 11 10 / Fax : 02 47 41 00 15

Important: Please follow manufacturer's recommendations.

Maintenance Guide

Omnisports Vinyl

24 10 2012

Periodical care or refreshment of the surface

A buffing will restore dull and worn areas. For the best result, use white pads, rotation speed 1000 rpm.

A periodical care can be done by using a cleaning machine like Rotowash B60 fitted out with nylon brushes or red pad, a floor cleaner (Dynatech Trophy) with a 10% dilution is recommended. Apply the mix (water/Dynatech Trophy) without vacuuming – Let the product soak into the floor for 5 minutes and then vacuum the surface.

Important: Please follow manufacturer's recommendations.

Stains removal

Spills should be wiped up quickly, by using a white clean cloth, before they have time to set, then clean the floor with clear water.

For stubborn stains on the floor (handball players resin for instance), on goal posts, on seats.... Spray Dynatech Trophy dilution 20%, let it work during 1 minute and sweep with a white clean cloth.

Important: Please follow manufacturer's recommendations.

Non sportive events


When organising non sportive activities (exhibitions, concerts...) in sporthall, it is required to protect the sport flooring. Tarkett Sports proposes a wide range of protection covering, such as:

ProtecTiles
Touchdown

For any further information please contact our Sales representatives or your regular Tarkett dealer.

Behaviour under heavy rolling load (cherry picker, forklift.....)

Before positioning of this kind of device on the covering you should protect the sport flooring –on all the rolling area - by using a double coat of 19mm plywood, these planks should be stacked but the junctions should not. This method tends to lower the pressure on the floor (weight distribution), and prevent the covering from being punched.



CAUTION, DO NOT USE:

Benzine, toluol, acétone, tétrachlororoethene, thinner, oilwax or strong scouring powders.....

Black rubber tires (pad on the feet of seats, bench.....) can cause permanent discolouration and should not be used.

If unsure, protect the floor by placing a piece of carpet, cardboard or similar material underneath.

The information given in this technical specification is indicative. It is based on our knowledge and experience. It has to be considered as general maintenance rules, which cannot integrate the particular data from each installation. Therefore, it is subjected to modifications whenever required.